

# ENGINEERING CHANGE NOTICE

## BEARHAWK LSA PLANS

### DRAWING #5

The AN 3 hole to mount the pulley bracket to the spar lower cap strip was dimensioned wrong @  $1\frac{1}{2}$ " from web splice  $\phi$ . Position should be  $\frac{15}{32}$ . Call me if you have already drilled your spar caps. 540-473-3661

lkt

Bob

